

# NO-BURN was there!!!

WHAT STARTED OUT TO BE A NICE EVENING DINNER COOKED ON AN OUTDOOR COOKING AREA COULD HAVE ENDED IN A HOMEOWNERS WORSE NIGHTMARE...



## Grill Fires

- Each year, an average of 6,500 grill fires result in nearly \$27 million in property loss.
- Most grill fires are associated with residences.
- Grill fires increase during warm weather months, corresponding to increased outdoor recreational activities.
- As the public increases its use of gas grills, the number of gas grill fires has increased significantly.
- Mechanical failure or malfunction is by far the leading ignition factor for grill fires.

Sources: NFPA and NFIRS

Grill area is located less than 10 feet from the main house



According to the homeowner, an unattended grill sparked a grease fire that burned for "at least ten minutes" until they realized the grill was on fire. When the homeowner finally came outside "the grill area was completely engulfed in flames."

The grill was framed with wood 2 x 4's and OSB sheathing and then coated with NO-BURN WOOD GARD MiH.

WHEN THE FIRE WAS PUT OUT AND THE WOOD WAS INSPECTED THE RESULTS WERE TRULY AMAZING...



No-Burn prevented the flames from spreading



No-Burn protected the wood framing



No-Burn protected the OSB wood

NOT ONLY WAS THERE VERY LITTLE DAMAGE TO THE WOOD SURROUNDING THE GRILL, THE FIRE DID NOT SPREAD TO THE SURROUNDING WOOD WHICH LEADS TO THE MAIN HOUSE.

*"I don't even want to think about what would have happened if the wood had not been protected with No-Burn!!"*  
- Homeowner

NO-BURN FIRE AND MOLD PROTECTION PROVIDED BY:

NO-BURN OF BEXAR COUNTY / (210) 240-7351 / NOBURN@SBCGLOBAL.NET / WWW.NOBURN.COM