

# Home Treated With No-Burn<sup>®</sup> Was Not Scorched During Lightning Strike!



Initial point of impact. Balcony was partially damaged. Also noticeable are the burn marks on the house wrap.  
(Overall view of the structure)



Lightning strike came and hit sheathing. Burn damage noticeable to house wrap.  
(Close up view)



Notice the charring around the nails of the floor joists. The nails were heated to the point that the surrounding area would have been fuel if the floor joists were not treated.  
(Second level flooring)

**Saturday, August 9<sup>th</sup>, 2008, Huntsville, Alabama** was experiencing severe weather, but for the local No-Burn<sup>®</sup> Dealer work continued as usual. After all, the homeowners, the custom home builder and the Dealers had schedules to keep, and who's to let a little rain ruin anyone's parade? After the treatment of the attic and some of the second floor, the scattered showers turned into severe weather. Lightning bolts, like razors shot across the sky and hit the second story, shattering 2x4's, melting the house wrap and scorching the nails hammered into the floor's engineered wood boards. "The plastic house wrap melted, but like the demonstration put on by D&D Safety Solutions, No-Burn<sup>®</sup> was put to the test and no fire occurred!" No-Burn<sup>®</sup>'s Madison and Morgan County Dealers have been working their business since 2006 and their service and applications have been recognized by the homeowners, the custom home builder and the Huntsville Fire Department.

*(Structure treated by D&D Safety Solutions, Certified No-Burn<sup>®</sup> Dealers located in Alabama)*



*Providing Fire and Mold Resistance Globally*

[www.noburn.com](http://www.noburn.com)